

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T1 & 42NR 5 E . . .

----- Chippewa ----- COUNTY  
(Drummond Island)

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 35 and 2 . . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . .

WITNESSES TO CORNER 12" Cedar S 4° E 91 links . . .

14" Hemlock N 22° E 50 links . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from two Cedar B.T.'s (down) in good condition.

Corner shown to us by Wesley Lehmann, District Forester.

Corner placed and witnessed February 28, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 3/19/56  
REGISTERED LAND SURVEYOR