

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 NR. 5 E

Chippewa COUNTY
Drummond Island

DESCRIPTION OF CORNER 1/4 Corner between Sec.'s 31-32

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 4" Cedar S 41° W 11 links

Marked "1/4 S NBT"

7" Cedar N 12° W 107 links

Marked "1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one pine B.T. S 52° E 11 links. B.T. burned and in poor condition, notch plain.

Found old stake on ground in proper position.

No evidence of recent use.

SURVEYORS SEAL

SIGNED

Billy D. Tucker
REGISTERED LAND SURVEYOR

DATE 5/22/57