MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 42 NR 5 ...

		Chippewa	COUNTY
		Drammend	Island
DESCRIPTION OF CORNER	Nitwess Cein	er te Section Cer	per cemmen te Sec. s 29-30-31-32
DESCRIPTION OF CORNER	MONUMENT_	1" pipe with 4"	brass cap
WITNESSES TO CORNER .	6" Cedar	S 36 B	92 links
	6" Cedar	W.C. BT" N 82 L	76 links
		WW.C. BIN	
			-

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed witness cerner 5.25 chs. east of section cerner.

Section Corner falls in lake.

Relecated Section Corner by extending old fonce line from east and a proportionate distance between east and west shore of lake.

Distance south from section cerner 29-30-31-32 to 1/4 cerner between Sec.'s 31-32 checks very good.

Note: Section corner lies 5.25 chs. west of witness corner and in lake.

SURVEYORS SEAL

SIGNED Silly Suchles DATE 6/19/57