MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T.42 NR 5 5

		Chippewa	COUNTY
DESCRIPTION OF CORNE	R Meander cerner be	Drummend Islan	
DESCRIPTION OF CORNE	R MONUMENT1"_1	pipe_with_4" brace	is cap
WITNESSES TO CORNER	7" Cedar	s 43° ¥	170 links
WITNESSES TO CORNER	Mari 4" W. Birch	red "M.C. MBT" M 25 W	23) links
	Mari	ced "NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced meander corner from Gov't notes of meanders of lake shore. Rocky shoreline has not changed and checks very well with notes.

Bearing to HE tip of Island No. 13 checks very good.

SURVEYORS SEAL