MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_42. NR _6. E. -

| | | | ChippewsCOUNT |
|-------------|----|--------|---|
| DESCRIPTION | OF | CORNER | Section corner_common-to-sections-26,27,34,35 |
| DESCRIPTION | OF | CORNER | MONUMENT_4"_Codar_stake |
| WIT TNESSES | ТО | CORNER | 8 Cedar - N. 73 E - 1.37 Chains |
| | | | No more witnesses available |
| | | | |
| | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by proportionate measurement, by Forestry Division Survey crew, while working in this area. Corner is in Southern portion of dry lake bed.

Corner was placed and witnessed August 11, 1950.

SURVEYORS SEAL

SIGNED SIENE (SURVEYOR DATE 12/27/50 -