

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 42. NR. 7. E. 2.

Drummond Island

Chippewa COUNTY

DESCRIPTION OF CORNER Beander Corner between Sections 25 & 26

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER

12" Cedar - N 56 E - 44 Links

8" Cedar - S 25 W - 13 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. One original B.T. still in place, down, in good condition.**

**Corner was placed and witnessed October 6, 1953.**

SURVEYORS SEAL

SIGNED

*James C. Anderson*  
REGISTERED LAND SURVEYOR

DATE 2/26/56