

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T~~42~~ & 43 NR 6 & 7 E.

----- Chippewa ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 36, 31, 6, 1

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 10" Cedar N 51° W 42 links

13" Cedar S 18° W 61 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner 36, 31, 6, 1 from two Tamarack B.T.'s in poor condition.

Corner shown to us by Wesley Lehmann, District Forester.

Corner near North edge of swamp.

Corner placed and witnessed May 2, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 5/11/56  
REGISTERED LAND SURVEYOR