

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42. NR. 7 East

Chippewa COUNTY
Drummond Island

DESCRIPTION OF CORNER section corner for sections 26, 27, 34, 35

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 5-14-58

3" white birch N 33°, E 45 links. Marked "NST"

16" cedar stump S 40°, W 97 links. Marked "No 7"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced at pile of stones according to testimony of Carl Schultz, Hermansville. Mr. Schultz visited this corner in 1926 and found evidence of an original corner. Corner has been used since that time with no question. Found several old blazes on down cedars at corner.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 6-12-59
REGISTERED LAND SURVEYOR