NTATIO

JAN 18 2001

## Chippewa County Remonumentation Corner

RECEIVED FOR RECORD CHIPPEWA COUNTY STATE OF MICHIGAN

CECTION

## LAND CORNER RECORDATION CERTIFICATE

93 DEC 29 PM 2: 48

For corners in Chippewa		riing Kequi	rement of Act 74, Mich. I	P.A. 1970 Ante Malite
	(County)	Located In:	Corner Code ≠	REGISTER OF DEEDS
1.	Public Land Survey	T 43N R 2E T R T R	B-1	
2.	Property Controlling in Section	T R S T R S T R	***************************************	
3.	Miscellaneous Property in Sec.	S T R S T R	The same of the sa	Register of Deeds Stamp & File Number
	Lot No, i	Recorded Plat		ABCDEFGHIJK

William L. Karr in a field survey on December 7 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: (B-1) North & Corner of Section 6 (T43N-R2E)

Corner not established in original survey.

EMA COMMINIONAL MAN CC = D 1963: Neal Sperhake, L.S. 7876 (Kimberly Clark Corp.). Witness Corner recorded Liber 3, Page 122 of the Chippewa County Corner Records. Re-established corner position midway between the Northwest and Northeast corners of Section 6 and held centerline of Gogomain Road for North-South position. Set a 1" pipe with stamped aluminum cap as a Witness Corner 33" Witnessed the Witness Corner. South.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County (B-1)Remonumentation Program.

Found a PK nail. Found the recorded Witness Monument 33.02' South of the PK nail. Ronald R. Bischer, L.S. 22428, has placed nails and L.S. tags in the side of witness objects in the area. Also found a railroad spike 19.99' to the East (South 1/4 Corner of Section 31). Distance East to the Northeast corner of Section 6 is 2622.11 (Sperhake - 2624.16'). Distance West to the Northwest corner of Section 6 is 2625.95' (Sperhake - 2625.16'). Accepted corner position as found and offset it prior to road reconstruction. Replaced corner after construction completed. Added two additional witnesses.

Note: Corner falls 0.15' North of the Township Line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a 3/4" x 24" iron with plastic "Chippewa County Remonumentation" Corner falls in centerline of Gogomain Road (East-West, paved). Falls 20' West of the centerline of West Bay Road to the North (North-South, gravel) OF MICH

	-		•	• •	The second of th
Witnesses:					WILLIAM L.
Anchor Pole	N62°E	62.64'	(existing nai	l & L.S.	22428 tad\ARR ** \
14" White Birch	S22°E	67 <b>.</b> 66′	(existing nai	l-no tag	, Common Wathless) **
14" O.D. Pipe with Stamped	South	33.02'	•		SURVEYOR STAGE
Aluminum Cap					No. 27450
8" Ash	S45°W	104.80'			27430
6" Balsam Fir	N32°W	65.92'			SUR SUR
South & Corner Section 31	/ East	19.99'		l 1	CHANGE
sianad by the State of the	• ·		Date 12	73/93	
Signed by		· · · — — — —			

J 27450 Surveyor's Michigan License No. 27450

Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination. Heristo MAY 14, 1975 REVISED JAH., 1983 Distances are to a nail in side of witness objects unless noted.