

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR. 6 E.

Chippewa COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 26 and 27

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 6" Cedar N 37° W 58 links

5" Cedar N 11° E 48 links

Road 75 links West

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

1/4 Corner has been perpetuated by unknown surveyor.

Iron Pipe and Concrete Monument in place.

Corner placed and witnessed May 3, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 5/11/56  
REGISTERED LAND SURVEYOR