

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 43.. NR. 6 E..

Chippewa

COUNTY

DESCRIPTION OF CORNER .. Section Corner common to Sections 26, 27, 34, 35

DESCRIPTION OF CORNER MONUMENT .. 1" pipe with 4" brass cap ..

WITNESSES TO CORNER .. 10" Cedar .. S 5° W .. 37 links ..

.. 10" Cedar .. S 70° E .. 62 links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner. Iron Pipe and Concrete Monument has been placed by unknown surveyor.

One White Pine B.T. in place; poor condition.

Corner placed and witnessed May 3, 1956.

SURVEYORS SEAL

SIGNED

*Billy D. Buckles*  
REGISTERED LAND SURVEYOR

DATE 5/11/56