

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR. 6 E.

Chippewa COUNTY

DESCRIPTION OF CORNER Meander Corner between Sections 22 and 23

DESCRIPTION OF CORNER MONUMENT No corner set

WITNESSES TO CORNER 5" Cedar S 5° W 60 links

9" W. Spruce S 74° W 20 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed M. C.

An Iron Pipe has been set by unknown surveyor many years ago.

M. C. lies 19 links East of 6.70 ch. marker from South (Bonners').

Corner found by Survey Crew while making a partial re-survey of this area.

Corner witnessed May 3, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 5/11/56
REGISTERED LAND SURVEYOR