

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR. 6 & 7 E.

Chippewa COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 25, 36, 30, 31

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Cedar N 86° W 100 links

Cedar N 30° E 61½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Replaced Section Corner from one Cedar stp. in proper position (badly burned).  
One Spruce in proper position (notch and part of face plain). Old Cedar stake  
in place.

Corner placed and witnessed May 4, 1956.

SURVEYORS SEAL

SIGNED *Billy D. Buckles* DATE 5/11/56  
REGISTERED LAND SURVEYOR