•	LAND CORNER RE	CORDATION CERTIF	ICATE	
For corners in	Filing Requirement	of Act 74, Mich. P.A	. 1970 RECEIVE	D Can access
Chippewa	Located In:	Sorner Code ##		D FOR RECORD
(County)		7017101 0000		CE MORES Y
1. Public Land Survey	TR		94 JUL 2	?2 AH11:11
	mer T 43N R 1E (A	-6		
Section Con	mer T 43N R 1E A	55	8. 20	gen Madolle
2. Property Controlling S _	T R			
in Section S _	<u>R</u>		REGISTER OF DEEDS	
	TR	1, 1	Register of De	eds Stamp & File Number
Property in Sec. S _				
4. Lot No, Record			A B	CDEFGHIJKL
5. Private Claims				
	1		3	
			4 7	- 8 - 9 - 10 - 11 - 12
! Keith R. Waters , in a				
do hereby certify that under requireme in lines 1 and 2 above were in confo				-17-16-15-14-1-1
current manual of survey instructions	of the United States Department of	of the Interior, Bureau of La	and 7	╌┼╌┼╌┼╌┼╌┼╌┼
Management or by a decree of a Court above were in conformance with the re				-20-1-21-1-22-1-23-1-2
Court of Law; established, re-estat			as	
expressed below: NOTE: Not more than 4 corners	all in the same town and ran	no mov ho rocarded	10 -30-	29 28 27 26 2
on this certificate.	, an in the same town and ran	ge, may be recorded	12 31	
A. Description of original monum			13	
East. Preserved loc 1992: Neil Hill reset 75.67' Corner Fence P Marker, S75E 133.46' & (A-5) From Chippewa (From MDOT Notes, 4-26- 1992: Neil Hill four 74.60' Guy Pole, S60W B. Description of corner evidence (A-6) Found corner &	South. Location Deter- cation prior to road of the prior to road of the prior to road of the prior to road of the prior to prior to prior to the prior to prior to prior to prior to the prior to prio	mined by fence 1 construction with 447 (L.7, P.357) therly Gate Position 1.74' Sec. Corner (1960 Survey): prior to road con (L.7, P.357). OE 116.11' 13" Ed in restoring or reestate corded in Liber	ine West and natural with N70W 72.82' t, East 75.64 r, South 2629 1" Iron pin onstruction. N40W 79.94' Clm, South 264 olishing corner:	brushed opening lesses. Power Pole, West 1' Top Center R/W 1.74' Sec. Corner 1 in monument box. Power Pole, S75E 11.74' 4 Corner.
County Records. Accep	oted corner position a	s found.		
(A-5) Found corner a County Records. Accep	and accessories as repted corner position a	corded in Liber s found. SURVEY &	7, Page 357	of the Chippewa
	DEI	MONUMENTATI	ON	TATE
	B 1 (som I	VICINOMERIAL		KEITH R
	1	JUL 2 6 1994		WATERS **
•			,	* SURVEYOR *
	·	COMMISSION		33142
Description of monument for a (A-6) ½" iron rod & a in monument box		(A-5) 1"	pin in monu	of the come AND sument box at M-48
In monument box East and M-129 WITNESSES WITNESSES				
N 70 W 72.82' J	Dan mare Tinii -	r		
	Power Pole Corner Fence Post	N 40 W S 75 E		Power Pole
	Southerly Gate Post	S 60 W		Guy Pole Power Pole
East 75.64' 9	Pop Center R/W Marker	S 50 E	116.11'	13" Elm
	B" Tamarack	South		4 Corner
	Section Corner Section Corner	at many		

vevor's Michigan License No. 33142

Wile: Bearings are compass bearings corrected for declination.

Bearings are to a nail in side of witness objects unless noted.

Bearings are to a nail in side of witness objects unless noted.

Date