MAR 0 9 1994

4. Lot No.

expressed below:

5. Private Claims __

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN

93 DEC 29 PM 2: 48 REGIŠTER OF DEEDS

Register of Deeds Stamp & File Number

2 3

9

10

11

12 13

For corners in Chippewa Located In: Corner Code ## (County) 1. Public Land Survey T44N R 1E -13\ Same T43N_R 1EV F-1)/Corner T _____ R ___ T _____ R _ 2. Property Controlling __ T _____ R ____ in Section S __ __ R ____ __ T __ 3. Miscellaneous ____ T ____ R ____ S_ Property in Sec. _ T __ __ R __

I, William L. Karr , in a field survey on December 18 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines $3,4\,\mathrm{and}\,5$ above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F-13) & Corner Common to Sections 33 & 4 (T44N-R1E)

1840: Corner established by Austin Burt for William A. Burt. Set & Section Post.

Fir 10

___ , Recorded Plat __

N58°W

23 links

Fir 11

NO9°E

29 links



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being re-established as part of the Chippewa County Remonumentation Program.

Found no evidence of original corner. Found a North-South fence line on the North side of the road. Re-established corner position on line between the Southeast and Southwest corners of Section 33 on the extension of a fence line to the North. Distance East to the Southeast corner of Section 33 is 2647.45. Distance West to the Southwest corner of Section 33 is 2649.05'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (F-13) Corner is a 3/4" x 24" iron with plastic "Chippewa County Remonumentation" cap. Falls 7' North of the centerline of Gogomain Road (East-West, paved). Falls on extension of fence line to the North. Falls approximately 16' West of extension of fence line to the South (fence is on East side of Drive).

Witnesses:

Corner Fence Post North 40.82' 3" Spruce N61°E 71.88' 6" Aspen S23°E 113,701 Power Pole (PD2/55/6) S69°W 174.67

Signed by __

Date

²7450 Surveyor's Michigan License No. NOTE: Bearings are compass bearings corrected for declination. FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYDRS, JAN. 28, 1971
REVISED MAY 14, 1975

Distances are to a nail in side of witness objects unless noted.

REVISED MAY 14, 1975 REVISED JAN., 1983

KARR LAND

SURVEYOR

No.

27450