

MAR 09 1994

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD CHIPPEWA COUNTY STATE OF MICHIGAN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

93 DEC 29 PM 2: 48

WILLIAM I KARR LAND SURVEYOR No.

	Filing Kequ	irement of Act 74, Mich. P.A.	
For corners in			V. Kore. M. hill
Chippewa	Located In:	Corner Code ##	J. Koza Maleik
(County)			REGISTER OF DEEDS
Public Land Survey	T <u>44N</u> R <u>1E</u> T <u>43N</u> R <u>1E</u> T <u>R</u> _ T R	I-13\ Same I-1 Corner	
2. Property Controlling	S T R	<u> </u>	
in Section	S T R		
3. Miscellaneous	_S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R	, , , , , , , , , , , , , , , , , , ,	
4. Lot No , F	Recorded Plat		
			2 - 6 - 5 - 4 - 1 - 3 - 2 - 1 -
			3
			4 - 7 8 9 10 11 12 -
ı, <u>William L. Karr</u>	, in a field survey onDece	ember 3 , 19 93	. 5
do hereby certify that under rec	quirements of P.A. 74, Michigan P.	A. of 1970, the corner points mentione	d 6 18 17 16 8 14 13
in lines 1 and 2 above were in	a conformance with regulations uctions of the United States Der	and rules therefore as required in the partment of the Interior, Bureau of Land	G 7
Management or by a decree of	a Court of Law and/or that the cor	rner points mentioned in lines 3, 4 and	5 8 13 30/141 22 23 24
above were in conformance wi	th the rules of the Michigan Board	d of Land Surveyors or by a Decree of	a / 4
	re-established, monumented, re	e-monumented, recovered, found a	10 30 29 28 27 26 25
expressed below:	•		11
		and range, may be recorded	
on this certificate.			12 31 32 33 34 35 36
A P THE SECOND		and/ar subsequent restoration:	13
		and/or subsequent restoration: ions 34, 35, 2 & 3 (T44	N_D1F\
(I-13) Section C	Country Read Commission	on Corner recorded in	Liber 3, Page 43 of the
	County Corner Records		and by rage 45 or and
Concre	te monument 33.0' No	rth (No description of a	actual corner).
COLLE		The transfer of the	

1993: G.A. Meyers, L.S. 28418. Corner recorded in Liber 8, Page 1 of the Chippewa County Corner Records. Found 14" iron pipe.

Power Pole \$25°W 89.28′ 10" White Pine N05°W 57.32′

10" Spruce S81°E 147.70'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I-13) This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found 1½" O.D. pipe with PK nail in it . Found 4" diameter concrete filled pipe with stamped brass tablet "State of Michigan No. 27". Monument is a Witness Monument from a 1930 Department of Conservation survey of Munuskong Bay State Park by C.M. Cade, C.E. Found the three record witness objects as recorded by Meyers. Record bearings to the objects are in error. Accepted corner position as found. Offset corner position prior to road reconstruction work. Replaced corner after construction was completed. Added an additional witness.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I-13) Corner is a 3/4" x 24" iron with plastic "Chippewa County Remonumentation" cap. Corner falls 1' North of centerline Gogomain Road (East-West, paved) and on the approximate centerline of Aldrich Road to the South (North-South, two track-seasonal).

Witnesses:		
4" Diameter Witness Monument	North	32.92' (existing)
10" White Pine	S26°E	57.32' (existing nail)
Power Pole	S25°W	89.24' (existing nail)
8" Maple	\$50°W	145.67'
12" Spruce	\$78°W	147.67' (existing nail)
- 1		7 1

Signed by Date 12 75(

Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination.

Distances are to a nail in side of witness objects unless noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED JAN. 1983