LAND CORNER RECORDATION CERTIFICATE

For	r corners in	Filing Require	ement of Act 74, Micl	h. P.A. 1970		4.00
	Chippewa			1	RECEIVED CON NO.	
	(County)	Located In:	Corner Code ##		RECEIVED FOR REC CHIPPEWA COUN STATE OF MICHIS	ľ V
1.	Public Land Survey	T _44N R _1W.	_M=12		94 JUL 22 AM 11	: 07
_	Section Corner Common to :	T 44N R 1W T 44N R 1E	_M=11 _A=11		J. Roge Made	ักส ^ร ์
2.	Property Controlling S in Section S	TR			. 12	
3.	Miscellaneous S			Regi	REGISTER OF DEE	DS & Eila Number
	Property in Sec. S	T R	<u> </u>	liegi	aser of peeds Statut	a rile number
4.	Lot No, Recorded	∣ d Plat				
5.	Private Claims				ABCDEF	GHIJKL
		,			2 6 5 - 4 -	╌┼╌┇╼┼╌┆╼
	·				3	-}-}- }-
۱, _	Keith R. Waters , in a li	eld survey on	BER 5 19	_93,	5	10-1-12-
dο	hereby certify that under requirement lines 1 and 2 above were in conform	its of P.A. 74, Michigan P.A. o	of 1970, the corner points n	nentioned	6 18 17 16	15 14 13
cur	rrent manual of survey instructions o	f the United States Departs	ment of the interior, Burea	u of Land	7	
abo	nagement or by a decree of a Court of overwere in conformance with the rul	Law and/or that the corner es of the Michigan Board of	rpoints mentioned in lines I Land Surveyors or by a D	3,4 and 5 ecree of a	B 192121-	
Co	urt of Law; established, re-establi pressed below:	shed, monumented, re-m	onumented, recovered,	found as	9	╂╂╂┼┼┼
	OTE: Not more than 4 corners,	all in the come town on	d manna man ba man		10 30 29 28	272625-
,,,	on this certificate.	an in the same town an	u range, may be recon	gea	12 31 32 32	
	Description of original monume				13	
В.	(M-12) From 1986 LCRC, Liber 6, Page 301: ½" x 18" iron & cap #27450 on M-129 centerline N89E 74.30' Top R/W Marker, N89W 74.20' Top R/W Marker, N68W 68.82' 12" Spruce 1992: Neil Hill reset ½" iron with cap #27447 (L.7, P.360). N89E 74.24' PK Top Con R/W Mkr, N89W 74.16' PK Top Conc R/W Mkr, N68W 68.97' MDOT Tag 12" Spruce, N85E 77.64' MDOT Tag Power Pole, N85W 75.39' MDOT Tag Power Pole, North 2629.47' Section Corner (M-11) 1979 LCRC, Liber 4, Page 269: Found monument box with iron as called for in MDOT right-of-way maps. N73E 79.40' Conc. R/W Marker, S75W 78.80' Conc. R/W mkr. 1992: Neil Hill found 3/4" iron and accepted (L.7, P.360). N73E 79.37' PK Top Conc. R/W Mkr., S75W 78.74' Conc. R/W Mkr (Broken), S50E 100.93' Power Pole, N70W 79.86' Cor FE Post, N25E 185.32' Power Pole Description of corner evidence found and/or method applied in restoring or reestablishing corner: (M-12) Found corner and all accessories as recorded in Liber 7, Page 360 of the Chippewa County Records. Accepted corner position as found. (M-11) Found corner and all accessories as recorded in Liber 7, Page 360 of the Chippewa County Records. Accepted corner position as found. SURVEY & SUR					
		† •	i., Vi))	E SI	VEITUR
			JUL 2 6 1	994	# **	KEITH R. WATERS
		es.	COMMIS	SION		LAND SURVEYOR A No.
⊃.	Description of manument for co	rner and accessories of	etablished to perpetuat	a locating the		33142
(M-12) %" re-rod & cap #27447 in (M-11) 3/4" rod in monument box Easterly Side of Monument WITNESSES						LAND SUSSE
						diame
	WITNESSES		17 FA F			
	N 89 E 74.24' PK	Top Conc R/W Mkr	N 73 E S 75 W	79.37' PK	Top Conc. R/W 1 nc. R/W Mkr (Bro	Mkr.
	N 89 W 74.16' PK	Top Conc R/W Mkg	S 50 E 1	.00.93' Pow	≈. ryw raer (aro zer Pole	oven)
	N 68 W 68.97' MD	OT Tag 12" Spruce	N 70 W	79.86' Cor	FE Post	
		OT Tag Power Pole OT Tag Power Pole		85.32' Pow	er Pole	
		ction Corner	•			
		,				
	1/'H ~ '	: \ 				
_	ned by Keith R. U	Lalen		25-5		
חנ	veyn's Michigan License No. NOIE: Bearings are com Distances are to a naj	33142		. FORM ADDROVE	D AY MICHIGAN CTAIR SOADS on t	ANN ENGVENAGE ING
	Distances are to a nail	i in side of with	rected for decliness objects unle	nation:""" ss noted.	O P. MICHANN STATE BUNNE OF I	ANO SUNVEYORS, JAN, 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983