

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Chippewa COUNTY


T 44N R 1-2W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 7-18-12-13

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 12/8/71

WITNESSES TO CORNER..... 14" Tamarack (S12 NBT) N17°W 17.0'



14" Tamarack (S13 NBT) S20°W 37.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at a 1" iron pipe, set by unknown surveyor.

Found a wood post and iron pipe but no evidence of original corner or witnesses.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

1/7/72

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68