

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Chippewa COUNTY
T 44N R 1W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 17-18-19-20

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 12/8/71

WITNESSES TO CORNER..... 15" Tamarack (S18 NBT) N16°E 37.6'



11" Tamarack (S17 NBT) N83°E 29.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at a squared tamarack, marked by unknown surveyor.

Found old blazes along line north of this corner.

Found no evidence of original corner or Hemlock witnesses.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

DATE

1/7/72

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68