## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. \_ Լվե \_\_\_\_ N.R. <u>1 W</u>

	Chippewa			COUNTY	
DESCRIPTION OF CORNER	North 1/8 Corner i	for Sections	s 10 <b>-1</b> 1		<del> </del>
CORNER MONUMENT	1" Pipe with 4" Al	Luminum Cap			
DATE MONUMENT PLACED AND	WITHESSED 5-21	:-62			
WITNESSES TO CORNER	. 6" Soft Maple	(1/8 BT)	s 50° W	55½ links	
10	7" Soft Maple	(1/8 BT)	n 65° w	72½ links	<del> </del>
CIRCLE CORNER REGISTERED	AND				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway between Section Corner to North and 1/4 Corner to South.

SURVEYOR'S SEAL