MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 1/1 W.R. 1 W

				Chippewa	COUNTY
DESCRIPTION OF CORNER	1/4 corne	er between Sec	ctions 10-11.		
CORNER MONUMENT	l" Pipe 1	with h Alumir	ıum Cap		
DATE MONUMENT PLACED AND	WITNESSED .	5-2h-62			
WITNESSES TO CORNER	. NBT's:	7" Soft Maple	(1/4 S NBT)	S 52° W	$171\frac{1}{2}$ links
10	AND				
CIRCLE CORNER REGISTERED	AND				

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two Section Corners.

Corner lies in line with old dead furrow to West.

Corner lies 1/2 chain East of Road.

SURVEYOR'S SEAL

D. Buckler DATE 8-23-63 Billy D. Buckler