## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 111 M.R. 1 W

|                                    |                 | Cr          | Chippewa |          |
|------------------------------------|-----------------|-------------|----------|----------|
| DESCRIPTION OF CORNER 1/4 Corne    | r between Secti | ons 3-10    |          |          |
| CORNER MONUMENT                    | ith 4" Aluminum | Cap         | * .      | ·        |
| DATE MONUMENT PLACED AND WITNESSED | 5-24-62         |             |          |          |
| WITNESSES TO CORNER NRT's:         | 7" Red Pine     | (1/4 S NBT) | n 50 w   | 66 links |
|                                    | 9" Red Pine     | (1/4 S NBT) | n 72° E  | 74 links |
| AND CIRCLE CORNER REGISTERED       |                 |             |          |          |

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two Section Corners. No evidence of original corner.

SURVEYOR'S SEAL

Silly Suckles DATE 8-23-63
REGISTERED LAND SURVEYOR
REJIEVED DATE 123-63

Billy D. Buckler