

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N.R. 6 W.


Chippewa COUNTY

DESCRIPTION OF CORNER 1/4 corner for south side Section 32

CORNER MONUMENT 1" iron pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9-19-63

WITNESSES TO CORNER..... 6" S. Maple (in a Lump) (N.B.T.) N. 41° E., 80½ Lks.



8" S. Maple (1/4 S.) (N.B.T.) N. 61° W., 163½ Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed Midway and on Line between section corners 1/2 mile to West and East.

Note: 1/4 Corner on North side of Section 5, T43N R6W lies 35½ Lks. East of this corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1/27/64
REGISTERED LAND SURVEYOR