MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 44 M.R. 6-7 W.

		Chippewa-Mackinac	COUNTY
DESCRIPTION OF CORNER _	1/4 Corner between Sections	13-18	
CORNER MONUMENT1"	Pipe with 4" Aluminum Cap		
DATE MONUMENT PLACED AND	D WITHESSED 9/24/63		
VITHESSES TO CORNER	9" Cedar (1/4 S. N.B.T.) N. 69° E. 102 Lks.	
N I	8" Cedar (1/4 S. N.B.T.) S. 75° W. 156 Lks.	
44-7	Corner lies on West edg	e of old Rail Road Grade.	
CIRCLE CORNER REGISTERED	AND		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established by Single Proportionate Measure along township line from original corners 1/2-mile North and 1 miles South.

Found a 24" W. Pine Stump scribed "1/4 S." bearing N. 65° E. 38 Lks. from Corner. Marks are very old. Possibly a Railroad Survey.

SURVEYOR'S SEAL

SIGNED Silly & Suchles DATE 1/27/64