

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Chippewa Co.

2 Corners.

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>44</u> N. S. R. <u>6</u> E. W.	<u>G-10, G-11</u>
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. S. R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S. R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-27, 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- G-10 East 1/4 Corner of Section 28. Found monument, this is Point of Beginning for Anguilm Plat of Trout Lake, set by R. Larsen, L.S. in 1946.
- G-11 N.E. Section Corner of Section 33. Found this corner as monumented by E.A. Sainio, L.S. 1955, as located by T.L. Jackson, L.S., corner is Point of Commencement for Betcher's Secound Plat in Section 27.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- G-10 Found 3/4" Pipe in Concrete, a Plat Monument set by R. Larson, L.S. 1948.
- G-11 Found bottom of Concrete Plat monument - broken off - 18" below surface. Distance east to Plat Monument = 20.1'. Distance North to Plat Monument = 90.1'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-10 1" pipe with 4" Aluminum Cap. Wit: N.W. Corner of Cabin, N62°E, 34.7' & S.W. Corner of Cabin, S71°E, 38.7' & Power Pole, S47°E, 4.7'.
- G-11 Set 1" x 14" Pipe on top of broken monument. Wit: Plat Monument, East, 20.1' & Plat Monument, North 90.1', Corner lies on east shoulder of road.

SIGNED BY _____

Billy D. Buckler

DATE 9-10-85

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

