

MAR 09 1994

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD STATE OF HICHIGAN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

93 DEC 29 PH 2: 48

For corners in Chippewa		i mig nequis	ement of Act 14, Mich. I	J. Rojen Madelle
		Located In:	Corner Code ##	Jan Marie
				REGISTER OF DEEDS
1.	Public Land Survey	T <u>44N</u> R <u>2E</u>	B-13	
		T R		
		T R		
		, TR		
2.	Property Controlling	S T R		
	in Section	S R		
3.	Miscellaneous	.S		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		Trogister of beeds ottamp & the Mulliper
4.	Lot No.	Recorded Plat		
	Private Claims	7,000,000		ABCDEFGHIJKL

William L. Karr in a field survey on _ <u>December 7</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: South 1/4 Corner of Section 31, (T44N-R2E)

1983: Harry W. Goodwin, L.S. 5434. Corner shown on a survey recorded in Liber 434, EVA COVER Page 692 of the Chippewa County Records. Survey does not state what is at

1979: Thomas M. Kelley, L.S. 24599. Corner recorded in Liber 4, Page 245 of the Work Chippewa County Corner Records. Found a 1" iron pin in centerline of Gogomaining Road opposite centerline gravel road to the North. The North & Corner of 61.37 Manning Section 6 is approximately 50' West of found corner. 12" Birch S03°E

24" Poplar N50°E 63.95

10

11

12

Power Pole S50°W 38.60′ (with old blaze)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found a railroad spike at intersecting centerlines of Gogomain and West Bay Road. It appears that the intersecting centerlines were used as best available evidence of 1/4 Corner position. The computed G.L.O. distance to the North 1/4 Corner of Section 6 (previously set at a split between Northwest and Northeast corners of Section 6; by (previously set at a split between Northwest and Northwest and Northwest Control of North Neal Sperhake, L.S. 7876) is 13.20'. Measured distance is 19.99'. Found no evidence of the North 1/4 corner of Section 6 as called for by Kelley. Numerous surveyors have accepted the position of this corner through the years. Ronald R. Bischer, have accepted the position of this corner through the years. Ronald R. Bischer, L.S. 22428, has placed nails and L.S. tags in witness objects in the area. Accepted corner position as found and offset it prior to road reconstruction. Replaced corner after construction completed. Added one additional witness.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a 3/4" x 24" iron with plastic "Chippewa County Remonumentation" Corner falls in the centerline of Gogomain Road (East-West, paved). Falls on the centerline of West Bay Road to the North (North-South, gravel).

Witnesses:

Signed by _

18" Aspen 14" White Birch Power Pole "V" Notch in West End of 24" C.M.P.	N41°E S10°E S38°W N17°W	63.80' 61.18' 38.27' 50.22'	(existing-added new nail (existing nail-no tag, o (existing nail & L.S. 22	common witness)
North 1/4 Corner Section 6	West	19.99′	Date 12/23/83	COUNTY OF THE PROPERTY OF THE

Surveyor's Michigan License No. 27450
NOTE: Bearings are compass bearings corrected for declination.

Revised May 14, 1975 27450 Distances are to a nail in side of witness objects unless noted.

REVISED JAN., 1983