			RNER RECORDATION CERT		
Fo	or corners in	riiliy neq	difement of Act 74, wich. I		
				RECEIVED FOR BLEGAD	
	Chippewa	Located In:	Corner Code ##	CHIPPEWA COUNTY STATE OF MICHIGAN	
	(County)			VIAIC OF THURIDAR	
				Oh 101 20 AM II. 10	
1.	Public Land Survey	T 45N_ R _1W		94 JUL 22 AM 11: 12	
		T 45N_ R _1E			
		TR		J. Rozer Madodh	
		T R		X. Aga Madille	
_		•			
2.	Property Controlling S	}	•	REGISTER OF DEEDS	
	in Section S.	T R		uraisten är beeds	
3.	Miscellaneous S	<u> </u>		Register of Deeds Stamp & File Number	
	Property in Sec. S	TR	·	regioter of becas oramp a the manuer	
	Troperty in dec.	·	-	······································	
		\		•	
4,	Lot No, Record	ded Piat		A B C D E F G H I J K L	
5.	Private Claims	<u> </u>	· · · · · · · · · · · · · · · · · · ·		
		1		2 - 6 5 4 3 2	
				3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		;			
				4 - 7 - 4 - 8 - 4 - 9 - 4 - 10 - 4 - 11 4 -	
١, ,	Keith R. Waters , in a	ifield survey on <u>ND</u>	VEMBER 18, 19 93	, 5	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned					
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					
	current manual of survey instructions of the United States Department of the Interior, Bureau of Land				
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					
Co	ourt of Law; established, re-esta	ablished, monumented,	re-monumented, recovered, four	ind as	
еx	pressed below:	:		10 30 29 27 26	
N	OTE: Not more than 4 corner	s all in the same tow	n and range may be recorded	4 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
***		s, an in the same tow	in and range, may be recorded		
	on this certificate.	:		12 31 32 33 34 34 35	
				13	
A.	Description of original monu	ment and accessories	and/or subsequent restoratio	n:	
	(M-6) Corner set by	Northwoods Land	Surveying, Inc.		
	THE OF COLLECT SEC DY	TOLUNIOONS ININ	burveying, Tic.		
	1987: Neil Hill reset	corner in mon.	box (Liber 7, Page 3	1).	
		1		·	
	East 7	73.61' P	ower Pole with Teleph	one	
			elephone Pole		
			" Jack Pine		
	S85°W 7	79.51' 1	.0" Jack Pine		
		İ	•		
		1		•	
В	Description of corner eviden	ce found and/or meth	od applied in restoring or rees	stablishing corner	
Ψ.	B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
	(M-6) Found corner and all accessories as recorded in Liber 7, Page 31 of the Chippewa				
	County Records. Acce				
	4	•			
		4		Miller	
		•	A11m1 (F) (A	Est OF MICHINA	
			SURVEY &	First of the second of the sec	
•			DEMONIUMENTATI	ON E STILL	
			REMONUMENTATI	7 7 •	
				H WATERS	
			1111 0 - 400 #	HT LAND TY	
			JUL 2 6 1994	V ★ SURVEYOR ★ #	
			•	No.	
			CONTRACTOR IN	W	
			COMMISSION	West and the second sec	
	•			OKO JAMA SULE	
		ì		William .	
_	Dudantus .				
U.	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
	(M-6) Corner is a 3" Rerod with cap #27450 in monument box.				
	WITNESSES				
	الأعطالا بإرياب بخبرك	1			
	n		. [13 1]		
	East 73.61'		with Telephone		
	N60°W 72.26'	Telephone F	ole (
	S65°W 98.00'	8" Jack Pin			
		1			
	\$85°W 79.51'	10" Jack Pi	716		
		1			
		•			
		· ·			
		1			

Surveyor's Michigan License No. 33142

NOTE: Bearings are compass bearings corrected for declination.

Distances are to a nail in side of witness objects unless that the surveyors are to a side of witness objects unless that the surveyors are to a side of witness objects unless that the surveyors are to a side of witness objects unless that the surveyors are to a side of witness objects unless that the surveyors are to a surveyors.

Date

Signed by