NOV 07 1994

Chippewa County Remonwentation Corner

COMM	ISSION	nio <u>y</u> realizationalite	ir Collici.		
		R RECORDATION CERTI	FICATE		
	Filing Require	ement of Act 74, Mich. P.	A. 1970	i 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	
For corners in			\$ 7.00	LAND CORNER	
Chippewa (County)	Located in:	Corner Code ##	\$ 2.00	MSSR	
(Courty)			18 OCT	94 1:02 P.M. RECEIPT# 70	0
1. Public Land Surve	ey T <u>45N R 1E</u>	G-13		RECEIVED FOR RECORD	
	T R			WA COUNTY - STATE OF MICHIGAN	
	T R		SHAKUN	H. KENNEDY, REGISTER OF DEEDS	
	Ť R			i	
2. Property Controlli				•	
in Section	S T R				
3. Miscellaneous	\$ T R		Register	of Deeds Stamp & File Number	
Property in Sec.	S T R			<u> </u>	
4. Lot No.	, Recorded Plat				
	11.000,000		^_	BCDEFGHIJK	L
			2	6	
			3 ├		+
		•	4	7 8 9 10 11	—12-
	arr , in a field survey on Dece mb		, 5	 	4
	der requirements of P.A. 74, Michigan P.A. were in conformance with regulations an	•	b t		—13-
	y instructions of the United States Depart	•	_		4
Management or by a dec	ree of a Court of Law and/or that the corne	r points mentioned in lines 3, 4 a	ındi5 a∐	19 20 15 21 22 23	_24-
	nce with the rules of the Michigan Board o	* *	Q I	1 1 1 1 1	Ī
Court of Law; establis expressed below:	shed, re-established, monumented, re-n	nonumented, recovered, tound	1 as	30 38 37 36	25.
	an 4 corners, all in the same town ar	d range may be recorded	11		
on this certif		id range, may be recorded	12		
on and certain	Touris.		13		
A. Description of ori	iginal monument and accessories and	d/or subsequent restoration:			-
(G-13) Star	ndard Corner of Sections 3	3 and 34 (T45N-R1E)		1	
<u> 1845:</u> J.H. N	Mullett, Set post.				
		links			
8"	Fir N58°W 10 3	Links	•	:	
 B. Description of co 	rner evidence found and/or method a	applied in restoring or reesta	ablishing corne	er:	
(G-13) This	s corner is being re-e	stablished as part	of the	Chippewa County	
Remonumentati	ion Program.				
Found no evic	dence of original corner.	Corner position was	re-establ	ished 17.82' West	
	2') of Closing Corner 4/3	on the extension of	a line fro	m Standard Corner	. (e
34/35 through	h Closing Corner 4/3.			Summing Control	
,				THIND SEAN COCHILI	
				\$ \$ \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
				1 / / / 2	111
				10/2/44 Pan	
•					H _S
	onument for corner and accessories eer is a 3/4" x 24" iron to falls in the centerline of 2" Spruce			THE PARTY OF THE P	ĭ
C Description of	nument for carner and coossession	astablished to parpatuate lo	cating the noe	ition of the corners within	
(G-13) Corne	er is a $3/4" \times 24"$ iron	with plastic "Chinn	ewa Comptu	Remonimentation"	
cap. Corner	falls in the centerline	of Eighteen Mile Rose	d. 45' Wes	t of an old feace	
to the North			, 1100	OF MICON	
	-			J	de
Witnesses:	2" Spruce	N45°E 64.	.33′		. W
	Closing Corner 4/3		82'	j j∗j KARR 🦠	* *
	10" Spruce	S76°E 109.		LAND SURVEYOR	*
	12" Scotch Pine		82'	No &	
	5" Scotch Pine		85' (not h	plazed 27450	<i>§]</i>
	POWER POLE LIBY/TUNE//LX) S64°W 64.	47'		1

Signed by

Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination.

Distances are to a nail in side of witness objects unless noted.

REVISED MAY 14, 1975

REVISED JAN., 1983 **27450**

Date