FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

2 Corners

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T45 N., R1 E.	K-12, I-9	1
2. PROPERTY CONTROLL- ING IN SECTION-	N. E. W. S., R W.		
3, MISCELLANEOUS PROPERTY IN SECTION	,T N. E. W.		i
4. LOT NO, RI	ECORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS ST
			FILING NUMBE

- A. Description of original monument and accessories and/or subsequent restoration:
- K-12 West 1/4 Corner of Section 36. Wood Post. OBT'S: Cedar 9, N57⁰W, 14 lks. & Birch 4, S66⁰E, 15 lks.
- I-9 N.W. Section Corner of Section 26. Wood Post. OBT'S: B. Ash 10, N41°E, 8 lks. & Fir 10, S69°W, 21 lks. Co. Surveyor F. Brown about 1925 no description of monument given. 16" S. Maple, N29½°W, 130.5' & Pole, N19°E, 80' & Pole, S7½°E, 109'.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- K-12 Set M.P.O.L. between the N.W. Section Corner and the S.W. Section Corner of Sec. 36.
- I-9 Set from stump of Co. Surveyor F. Browns N.W. N.B.T. A 23" S. Maple, N29½0W, 130.5'. Corner falls in center line of N-S blacktop road and in line with a graded road East.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- K-12 D.N.R. Monument. Bearings: 12" Aspen, S25°W, 44.1' & 6" R. Maple, S6°W, 56.7' & 8" Cedar, S55°E, 57.4' & 12" Aspen, N46°E, 43.7'.
- I-9 1" pipe W/plastic RLS Cap buried in center line of North and South Road. Bearings: 14" Aspen, \$500W, 96.9' & 5" Spruce, \$880W, 69.05' & Tag in Power Pole, \$87.25' & Tag in Power Pole, \$85.35' & 16" Maple Stump, \$890W, 130.5'.

SIGNED BY Lavil 13.	Bablitt	DATE_ 9-17-84		
David B. Babbitt	-			

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558