APR 2 6 1995

CHIPPEWA COUNTY REMONUMENTATION CORNER

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	i iiiig mequ	Hemenroi vor 14 mon i ve	1010
For corners in			
Chippewa	Located In:	Corner Code ##	
(County)	Cocated III.	Comer code	
			\$ 7.00 LAND CORNER
1. Public Land Survey	T <u>44N</u> R <u>1W</u>	A-1 Same	\$ 2.00 MSSR .
	т <u>45N</u> R <u>1W</u>	(A-13) Corner	5 DEC 94 12:36 P.M. RECEIPT# 1520
	T 44N R 2W	M-1 /(Township	RECEIVED FOR RECORD
	т <u>45N</u> R <u>2W</u>	M-13/ Corner)	CHIPPEWA COUNTY - STATE OF MICHIGAN
2. Property Controlling	S R	OF MICH	SHARON H. KENNEDY, REGISTER OF DEEDS
in Section	STR <u>/</u>	7(1)	
3. Miscellaneous	STR	KEITH R.	Register of Deeds Stamp & File Number
Property in Sec.	STRR	WATERS	
, ,	<b>∀</b> *	LAND *	
4. Lot No,	Recorded Plat ★	SURVEYOR **	—— ABCDEFGHIJKLM
5. Private Claims		No.	
	$\boldsymbol{\psi}$	33142	2 - 6 - 5 - 4 3 2 1 -
•	`	WED LAND SUBS	3
		WIND THE	4 7 8 9 10 11 12
Keith R. Water	s in a field survey onNov	zember 11 <sub>19</sub> 94	5
do hereby certify that under re	equirements of P.A. 74, Michigan P.	A. of 1970, the corner points mentione	
		and rules therefore as required in th	
		artment of the Interior, Bureau of Lan mer points mentioned in lines 3, 4 and	
		d of Land Surveyors or by a Decree of	
Court of Law; established, re-established, monumented, re-monumented, recovered, found as		as <sup>3</sup>	
expressed below:			10 30 29 28 27 25
NOTE: Not more than 4	corners, all in the same town	and range, may be recorded	11
on this certificate			12 31 32 33 34 35 36
			13

- A. Description of original monument and accessories and/or subsequent restoration:
  - A-13 (T45N, R1W) Corner Common to T44N, R1W, T45N, R1W, T44N, R2W & T45N, R2W.
  - Original ties to post: Cedar 12, N47°E 08 links Pine 14, S75°W 17 links.

    1978 As recorded in liber 1, page 366, Chippewa County corner records, by
    Thomas M. Kelly, R.L.S. 24599. Found 2" pipe and decayed post matching
    County Surveyor notes dated October 1913. Witnesses: 12" White Birch,
    N80°E 18.69' 6" Pine, S66°W 19.13' 8" Pine, N40°W 33.88'
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - A-13 (T45N, R1W)
    This corner is being perpetuated as part of the Chippewa County
    Remonumentation Program.
    Found a 2" iron pipe 3 feet above ground in a swampy area approximately 1200
    feet west of a north-south 2-track road west of the Chippewa County
    International Airport. I located this pipe in a previous survey in 1987 and
    it checked well with other corners in area as shown on a sketch done by Thoma

it checked well with other corners in area as shown on a sketch done by Thomas M. Kelly, R.L.S. 24599. Also found a previously blazed spruce northeast of corner which matches distance shown in liber 1, page 366, to what appears to be mistakenly labeled a 8" pine. The bearing to the pine also appears to be mistakenly shown as Northwest instead of Northeast. Accepted corner position as found and replaced pipe with a 3/4" x 48" rebar and aluminum Chippewa County Remonumentation cap. Laid 2" pipe next to 3/4" rebar.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-13 (T45N, R1W)

Corner is a 3/4" x 48" rebar with 3½" aluminum Chippewa County Remonumentation cap. Witnesses:

6" Balsam Fir, N04°E 45.08'

Note: Distances are to a nail and tag in the side of the tree. Trees are blazed a

10" Spruce, N46°E 33.98'	the side of the tree. Trees are blazed a
11" Spruce, S63°E 35.74'	and painted. Bearings are compass
5" White Birch, S46°W 21.13'	bearings corrected for declination
•	A COLUMN TO THE PARTY OF THE PA

Signed by Keite R. Water	Date (2-1-94	6 11/18/59
signed by		11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Suppover's Michigan License No. 33342		