LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970			
For corners in Chippewa	· ·	I	RECEIVED FOR RECORD
(County)	Located In:	Corner Code ##	CHIPPEWA COUNTY STATE OF MICHIGAN
Public Land Survey	T 45N_R _1W_ T 45N_R _1E_ T R T R	A-6/Corner	94 JUL 22 AM II: 12 J. Loga Madelle
2. Property Controlling S .			
in Section S	T R		REGISTER OF DEEDS
3. Miscellaneous S. Property in Sec. S.	T R T R	· · · · · · · · · · · · · · · · · · ·	Register of Deeds Stamp & File Number
4. Lot No, Record	ed Plat		A B C D E F G H I J K L M
5. Private Claims			2 6 5 4 3 2
			3
, Keith R. Waters , in a	i Healalannan an kilmb	IF ADER IR	4 7 4 8 4 10 4 11 4 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Beard of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			
NOTE: Not more than 4 corner: on this certificate.	s, all in the same town	and range, may be recorded	11 12 31 32 33 34 35 36
	•		13 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: (M-6) Corner set by Northwoods Land Surveying, Inc.			
1987: Neil Hill reset corner in mon. box (Liber 7, Page 31).			
N60°W 7 S65°W 9	/2.26' Te /8.00' 8"	wer Pole with Telephone lephone Pole Jack Pine "Jack Pine	•
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (M-6) Found corner and all accessories as recorded in Liber 7, Page 31 of the Chippewa County Records. Accepted corner position as found.			
		SURVEY & REMONUMENTATION JUL 2 6 1994	* WATERS *
		JUL & 6 1334	SURVEYOR * H
		COMMISSION	13142 LAND SUNT
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (M-6) Corner is a 3" Rerod with cap #27450 in monument box. WITNESSES			
East 73.61'	Power Polo	ith Telephone	
N60°W 72.26' S65°W 98.00' S85°W 79.51'	Telephone Po 8" Jack Pine 10" Jack Pin	le	
	i !		: - - - - - - - - - - - - - - - - - - -
- V'H O /	. \	_	
Signed by Kull R C	22240	Date/	-22-94
Burveyor's Michigan License No. NOIE: Bearings are co Distances are to a na	33142 mpass bearings c ail in side of wi	orrected for declination tness objects unless no	IRM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 PREVISED MAY 14, 1975 REVISED JAN., 1983
)		