

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Chippewa
(County)

Located In:	Corner Code ##
T <u>45N</u> R <u>1W</u>	<u>M-8</u> Same
T <u>45N</u> R <u>1E</u>	<u>A-8/Corner</u>
T _____ R _____	_____
T _____ R _____	_____
S _____ T _____ R _____	_____
S _____ T _____ R _____	_____
S _____ T _____ R _____	_____
S _____ T _____ R _____	_____

RECEIVED FOR RECORD
CHIPPEWA COUNTY
STATE OF MICHIGAN

94 JUL 22 AM 11:13

J. Roger Malott
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Keith R. Waters, in a field survey on OCTOBER 26, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M-8) From Land Corner Recordation Certificate, recorded 1-14-86, in Liber 29: "Set a 1/2" iron with LS 27450 cap on line between the Northwest and Southwest corners of Section 19 and on the extension of existing fence lines to the East and West.

1987: Neil Hill found 1/2" iron with cap and accepted (Liber 7, Page 32).

N36°E	124.92'	Power Pole
East	80.06'	Corner Fence Post
S22°E	185.12'	Power Pole
S83°W	68.14'	Power Pole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M-8) Found corner and all accessories as recorded in Liber 7, Page 32 of the Chippewa County Records. Accepted corner position as found.

SURVEY &
REMONUMENTATION

JUL 26 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M-8) Corner is a 1/2" iron with LS #27450 cap.

WITNESSES

N36°E	124.92'	Power Pole
East	80.06'	Corner Fence Post
S22°E	185.12'	Power Pole
S83°W	68.14'	Power Pole



signed by Keith R. Waters

Date 7-22-94

Surveyor's Michigan License No. 33142

NOTE: Bearings are compass bearings corrected for declination.
Distances are to a nail in side of witness objects unless noted.