
Signed by



JAN 1 8 2001

LAND CORNER RECORDATION CERTIFICATE

	CT	OM Filing Requi	rement of Act 74, Mich.	P.A. 1970
Fo	r corners in			PECCHYCO CON SCHOOL
	Chippewa (County)	Located In:	Corner Code ##	RECEIVED FOR RECORD CHIPPEWA COUNTY STATE OF MICHICAN
	(Coamy)			STATE OF MICHICAN
1.	Public Land Survey	Sec. 1 T 44N R 1W	_M-1	94 JUL 22 AM 11: 07
	Twp. Corner {	Sec. 36 T 45N R 1W	M-13)	JA SOL ZZ AMIII U /
	Common to: {		A-1	0.00 1.
	{	Sec. 31 T 45N R 1E	A-13	J. Kojir Madock
2.	Property Controlling	S T R		1 1 Common of the common of th
	in Section	S T R		REGISTER OF DEEDS
3.	Miscellaneous	S R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		register of Deeds Stamp & File Number
		•		
4.	Lot No	, Recorded Plat		A B C D E F G H ! J K L
5.	Private Claims			
				2 6 4 5 4 4 3 1 2 1
				3
		_		4 7 7 8 9 10 10 1
ι, _	Keith R. Waters	🛂 , in a field survey on 🔼 🗀 🥆	TOBER 10 , 19 9:	3
		requirements of P.A. 74, Michigan P.A		
		e in conformance with regulations a structions of the United States Depa		-1
	•	of a Court of Law and/or that the corn		
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a				1 1 2 1 2 1 2 1 2 2 1 2 3 1 2
	•	d, re-established, monumented, re-	-monumented, recovered, for	und as
exp	pressed below:			10 30 29 29 27 26 27
NO		4 corners, all in the same town a	and range, may be recorde	d 11
	on this certifica	te.		12 31 32 33 34 35 3
		al monument and accessories ar		13
В.	N 75 W N 73 E N 33 W Description of corne (M-1) Found co	57.93' MDOT Tag in 57.49' MDOT Tag in 77.01' MDOT Tag in 1132.66' Southeast Correvidence found and/or method	7" Poplar Power Pole rner Concrete Porch applied in restoring or ree es as recorded in I	stablishing corner: Liber 7, Page 366 of the Chippewa
		· ·		KEITH R. WATERS LAND SURVEYOR No. 33142 LAND LAND SURVEYOR No.
C.	Description of monu (M-1) Boat spil	ment for corner and accessories ke in monument box near	established to perpetuate East Edge of M-129	locating the position of the corner: at East-West Road.
	Witnesses:	S 77 E 58.09'	Found Spike	in 14" Spruce
		S 77 E 57.93'	MDOT Tag in	
		N 75 W 57.49'	MDOT Tag in	
		N 73 E 77.01'	MDOT Tag in	
		N 33 W 132.66'	Southeast C	orner Concrete Porch

Surveyor's Michigan License No. 33142

NOTE: Bearings are compass bearings corrected for declination.

REVISED MAY 14, 1975

Distances are to a nail in side of witness objects unless noted.

| IREP 2 PAGE 303 LIBER 8 PAGE 303

ŝ

7-22-94