

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 NR. 1 West

Chippewa COUNTY

DESCRIPTION OF CORNER section corner 21 - 22 - 27 - 28

DESCRIPTION OF CORNER MONUMENT 1" pipe with 1/2" brass cap

WITNESSES TO CORNER 6-5-52

28" maple clump N 26 $\frac{1}{2}$ <sup>0</sup>, E 156 links. Marked "LPT"

26" oak N 64<sup>0</sup>, E 92 links. Marked "LPT"

28" oak S 18<sup>0</sup>, W 161 $\frac{1}{2}$  links. Marked "LPT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced corner as perpetuated by unknown surveyor. Found record of this corner in county surveyor's office, Sault Ste. Marie. Found two iron pins in place also broken blow point. Re-scribed new bearing trees as recorded. Trees scribed "LPT". Corner lies 70 links south of old stone fence and 22 links north of woods road.

SURVEYORS SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR  
DATE 6-1-52