

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 45. NR. 1 West

Chippewa COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 15 and 22

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 6-5-58

3" cedar S 26° E 15 links. Marked "6558"

5" b. ash S 12° W 6 links. Marked "4558"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

**RESTORED.** Re-established 1/4 corner midway and on line between two section corners. Found numerous cedar stumps in vicinity but no evidence of original bearing trees. Corner placed and witnessed 6-5-58 with Daniel Bonner, Asst. District Forester. Corner lies 2 chains south of old railroad grade.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 6-18-59  
REGISTERED LAND SURVEYOR