APR 0 7 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner

For corners ECTION

Chippewa County Located in: Corner Code # 1. Public Land Survey **T45N R2W** F-6 T R T R T R 2. Property Controlling S T R in Section S T R Miscellaneous. S Ţ R Property in Sec. S

\$7.00 LAND CORNER \$2,00 MSSR

6 Mar 1998 1:41:09 PM Receipt #6451 RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

HARACE JAK MERMANISTAN PROMISTAN

BOOK 10 PAGE 177

2 3

5

7

8

9

10

11

12

13

31

- 32

33

Register of Deeds Stamp & File Number

25

RENA CO.

4. Lot No.

, Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on November 11, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-6 1/4 Corner common to Sections 16 & 17, Town 45 North, Range 2 West

- 1849 Original corner (sugar maple post) was established by Harvey Mellen, D.S. Witnesses: Lynn 8, S47°E 44 links - Lynn 12, N11°W 35 links
- 1908 Chippewa County Surveyor Frederick H. Brown notes indicate an original corner. Witnesses: Maple 8, N841/2°W 21' - Edison Pole, N481/2°E 29'
- 1924 County Surveyor Brown again indicates an original corner, put in monument and post.

Circa 1930 - County Surveyor corner tie book show the corner as a 24" cement post. Witnesses: Corner of School, N36°W - Maple, N881/2°W 21' - Mon., S51°W 28' - Maple 8, S76°E 38' - Pole, N51°E 27' - Maple 5, N31°E 36'

- 1990 LCRC liber 7, page 307, Gerald L. Wiggins, RLS 23521. Set corner at found iron car spring, this corner was set by County Surveyor in 1924. Placed a 1" pipe with a plastic DNR cap at corner position. Witnesses: 6" Maple, N50°E 17.6' - 12" Maple, N31°E 36.7' - 14" Maple, N20°E 28.2' - 4" Maple, N24°W 24.2'
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program. Found a 1" iron pipe with a plastic DNR cap and all four bearing trees as called for in above mentioned LCRC. Accepted corner as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 1" iron pipe with a plastic DNR cap at the corner position, which falls at the approximate centerline P.I. of a curve in Thompson Road to the south and east. Witnesses:

8" Maple, N45°E 17.72' 13" Maple, N26°E 37.10' 14" Maple, N16°E 28.81' 5" Maple, N26°W 24.20'

Note: Distances are to a nail/tag #33142 in the side of the tree. Bearings are compass bearings corrected for declination.

E OF MICHIGAN KEITH R. WATERS PROFESSIONAL SURVEYOR No. POFESSION

Keite R. Wat

Date 12-30-97

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995