PK. 11/2/97

APR 0 7 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Cornes 7.00 LAND CORNER

For corners iSECTION

Chippewa County Located in: Corner Code # 1. Public Land Survey T45N R2W F-11 7 R Ί R T R 2. Property Controlling T R in Section S T R Miscellaneous S Ŧ R Property in Sec. S

\$2.00 MSSR

6 Mar 1998 1:51:05 PM Receipt #6451 RECEIVED FOR RECORD

10

action that the state of

CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEFOR

BOOK 10 PAGE 185

6

8

9

10

Register of Deeds Stamp & File Number

4. Lot No.

, Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on October 27,1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-11 1/4 Corner common to Sections 28 & 33, Town 45 North, Range 2 West

1849 - Original corner (cedar post) was established by Harvey Mellen, D.S. Witnesses: Fir 7, N71°E 85 links Black Ash 6, S63°W 87 links

1908 - Chippewa County Surveyor Frederick H. Brown notes for Section 28 show a distance of 5249 feet on the south side, with distances of 26241/2 feet on each 1/2 mile. No specific mention is made of the 1/4 corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Chippewa County Remonumentation Program. Found no evidence of the original corner monument or its accessories. Reestablished corner on line between section corners 2620.45 feet east and 2627.50 feet west, on the extension of an old fence line to the north. Corner falls in the approximate centerline of an east-west gravel road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

Placed a 3/4" x 24" rebar with a plastic Chippewa County Remonumentation cap at the corner location, which falls in the approximate centerline of an east-west gravel road (17 Mile Road). Witnesses:

Power Pole (E19), N45°E 47.44' Power Pole, N86°E 275.54' Power Pole, N80°W 208.61' Center of Top of Gas Pipeline Marker, S04°W 35.98'

Note: Distances to poles are to a nail/tag #33142 in the side. Bearings are compass bearings corrected for declination.



Signed by Keith R. Walu

Date 12-30-97

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED JAN., 1983

PAGE 10

REVISED OCT., 1995