LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		
Chippewa	Located In:	Corner Code ##
Public Land Survey	T 43N R 2E	- G- 9
	T R `	
	T R "	
	Ť . <u>.</u> R	****
2. Property Controlling	S T. R	

Register of Deeds Stamp & File Number

4. Lot No. ______ , Recorded Plat ______


5. Private Claims

in Section
3. Miscellaneous

Property in Sec.

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



- G-9 Section Corner common to 21,22,28,29. Corner set by Billy D. Buckler R.L.S. on 7-7-75. No witnesses were available at that time.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 6-9 Marked new witnesses trees at Buckler's corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- G-9 Buried 1" X 14" Iron Pipe in road.

6" Oak clump, \$46°W, 26.55'

8" Oak Clump, N78°W, 79.45'

10" R. Pine, N40°E, 48.25'

6" R. Pine, N39°W, 45.55'

igned by Gerald L. Wiggins 23

Date 6-27-91

FORM APPROVED BY MICHOGAN

