## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in CHIPPENA					
	(County)	Located In:	Corner Code ##		
1.	Public Land Survey	T 45N P _ 2N_			
		T <u>45N R 2N</u>	63		
		T45N FI2N	66		
		T A			
2.	Property Controlling	S T R			
	in Section	S T R ,			
3.	Miscellaneous	·S T R		Regist	
	Property in Sec.	SIR		negisi	

ter of Deeds Stamp & File Number

4.	Lot No , Recorded P	at
_	Drivete Claims	

I. \_ Stephan J. Szyszkoski\_, in a field survey on \_ November 26, 1991 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented recovered found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration;
  - (61) CORNER NOTED IN RECORD OF CHIPPENA COUNTY SURVEYOR F.H. BROWN (1920): "THIS CORNER WAS PROBABLY MADE BY MEASURE FROM COR. I MILE EAST, AN ORIG. COR. I LOOKED FOR IT WHEN I RAM THE E-W 1/4 LINE IN SECTION 3...", AND LATER: "AN ORIGINAL CORNER WAS THERE WHEN I SURVEYED THE LINE FOR A ROAD AND FOR A FARMER." CORNER RECORDED BY CHIPPENA COUNTY ROAD COMMISSION IN 1977 AS 1"x18" IRON PIPE NETH FOLLOWING TIES: R.E.A. 42.45' SW, R.E.A. 45.45' SE.
  - (63) CORNER NOTED IN COUNTY SURVEYOR RECORD BY F.H. BROWN CO. 1923 AS "AN DRIGINAL COR. THE STUMP OF THE DRIGINAL OAK STANDS THERE TODAY AND A BAS PIPE IN RAVINE AT E. END OF CULVERT MARKS THE COR." CORNER RECORDED BY CHIPPENA COUNTY ROAD COMMISSION AS A 1" BOLT IN 1962 WITH THE FOLLOWING BT'S: N75E 51.10' TK. IN 12" POPLAR; N40E BO.65' TK IN 10" BIRCH; S50E 71.95' TK IN 10" SPRUCE.
  - (66) CORNER PREVIOUSLY RECORDED BY CHIPPENA COUNTY ROAD COMMISSION AS 1"x18" IRON PIPE WITH THE FOLLOWING BT'S: TK IN 4" MAPLE 63.70"
- B. STEET TK IN 10 MAPLE 45.50 SN

  B. STEET TK IN 10 MAPLE 45.50 SN

  Corner evidence found and/or method applied in restoring or reestablishing corner:
  - (61) FOUND AND ACCEPTED A 1° IRON PIPE 3'N AND 1'N OF INTERSECTION OF ROAD CENTERLINES. R.E.A. POLES ARE LACKING.
  - (63) FOUND AND ACCEPTED 1" POLT AT THE SURFACE OF DITUMINOUS PAVENENT OF BOUND ROAD IN THE CENTER OF A FILLED RAVINE. TWO REMAINING CCRC BT'S CHECK AS FOLLOWS: NBOE 50.5' 18" POPLAR WITH OLD BLAZE; N50E BO.5' 12" BIRCH WITH OLD BLAZE.
  - (66) FOUND AND ACCEPTED A 1° IRON PIPE AT THE SURFACE OF BITUMINOUS PAVEMENT OF BOUND ROAD. CCRC TIE TO 10" MAPLE CHECKS TO A 12" MAPLE S60M.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. 863 FOUND 1" 180N PIPE, S63N 60,62" SET (63) FOUND 1" 180N BOLT. 525N 118.15" (66) FOUND 1" 180N PIPE, 863N 57.7" NAIL AND MONR TAG IN CORNER FENCE POST; 575W 45,15' STOP SIGN POST; N7BE 49.20' STOP STON POST; SAGE 74.12' SET HAIL AND SOUTH SIDE DRIVENAY; S75M 46.7' CENTER HONR TAG IN HE FACE PONER POLE.

SET HAIL AND HONR TAG IN POWER POLE; SSAW 58.3" CENTER OF 4" STEEL GATE POST OF 4" STEEL GATE POST NORTH SIDE BRIVENAY: MSSW 64.4" SET MAIL AND MONR TAG IN S. FACE B' POPLAR: SAGE 62.36" SET NATL AND MONR TAG IN N. FACE 14" FIR. FOUND TAS \$16041 IN N. FACE 12" MAPLE; 560N 65.4' FOUND TAG 816041 IN E. FACE 12" MAPLE; \$50E 58.55" FOUND CAP #245?? IN S. FACE 7" MAPLE: N26E 84.6' SET NAIL AND MONR TAG IN 7" N. BIRCH.

STEPHAN J

Surveyor's Michigan License No. 35984

SZYSZKOSKI LAND Date \_//-27-9/ SURVEYOR