

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

✓

LAND CORNER RECORD


Chippewa COUNTY
T 45N R 7W

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 14-15

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/3/71

WITNESSES TO CORNER..... 9" Cedar (¼S NBT) N69°W 26.8'



9" Cedar (¼S NBT) S2°E 25.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner replaced from two original witnesses; a Cedar, N64°E, 15 links, Tree down; a cedar stump, S6°W, 07 links, part of lower scribe marks remaining.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

DATE 1/10/72

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68