

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Chippewa COUNTY


T 45N R 7W

DESCRIPTION OF CORNER West 1/16 Cor. bet. Secs. 24-25

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/2/71

WITNESSES TO CORNER..... 9" Cedar (W1/16 BT) S45°E 24.0'



15" Cedar (W1/16 BT) N33°E 34.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner placed midway and on line bet. Sec. Cor. to west and $\frac{1}{4}$ Cor. to east.

Corner lies in line with an old e-w logging road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

1/7/72

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68