

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45-46N N. R. 7W


Chippewa COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 4-33

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-27-62

WITNESSES TO CORNER..... 8" Cedar (1/4 S NBT) N 40° W, 18 links



8" Cedar (1/4 S NBT) N 58° E, 16 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one tamarack B.T. bearing N51°W, 17 links. Tree down and badly rotted. Found evidence of upper face and overgrowth. Found old stump bottom for second tamarack B.T.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 7, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler