

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45-46N N.R. 7N


Chippewa COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 3-34

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 9-27-62

WITNESSES TO CORNER..... 9" Cedar (S $\frac{1}{4}$  NBT) S45°W, 53 $\frac{1}{2}$  links



8" Cedar (N $\frac{1}{4}$  NBT) N44°W, 46 links

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This corner re-established midway and on line between two section corners. Found no evidence of original corner.

**SURVEYOR'S SEAL**

SIGNED Billy D. Buckler DATE March 7, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler