

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Luce and Chippewa COUNTY


T 45N R 7-8W

DESCRIPTION OF CORNER Section Corner common to Secs. 30,31,25,36

CORNER MONUMENT 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED 10/20/60 with Frank J. Bray

WITNESSES TO CORNER..... 13" Hard Maple (S31 NBT) S46°E 71 links



8" Hard Maple (S 36 NBT) S33°W 75½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by proportionate distance along township line.

Found numerous blazes at corner.

SURVEYOR'S SEAL

Billy D. Buckler

SIGNED

Billy D. Buckler

DATE

5/25/61

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
✓ Forestry Div., Lansing

R 4047
Rev. 10/68