

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 7W


Chippewa COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 10-11-14-15

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 11-5-68

WITNESSES TO CORNER..... 10" Cedar (S14 NBT) S31°E 4.6'



9" Cedar (S11 NBT) N58°E 20.0'

11" W. Pine (S10 NBT) N14°W 17.7'

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an old wood post, from remains of two original witnesses;
both in poor condition.

Corner lies in Cedar swamp.

SURVEYOR'S SEAL

Billy D. Buckler

SIGNED

Billy D. Buckler

DATE

1-20-71

REGISTERED LAND SURVEYOR