

MAY 28 1997

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

\$7.00 LAND CORNER

\$2.00 HSSR

5/4/1997 2:13:14 PM

Receipt #294

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

COMMISSION
For corners in

Chippewa County	Located in:	Corner Code #
1. Public Land Survey	T46N R2W	D-9
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

BOOK 10 PAGE 68

Register of Deeds Stamp & File Number

I, William L. Karr, in a field survey on December 16, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D-9) 1/4 Corner Common to Sections 20 & 29, T. 46 N., R. 2 W.

1849 H. Mellen set sugar maple post for 1/4 corner in original survey.

Witnesses: Cedar 12 S 80° E 12 lks
Hemlock 14 N 25° W 13 lks

1916 F.H. Brown, County Surveyor, surveyed portions of section 20, but does not note finding anything at the S. 1/4 corner or running the South line.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D-9) 1/4 Corner Common to Sections 20 & 29, T. 46 N., R. 2 W.

This corner is being reestablished as part of the Chippewa County Remonumentation Program.

Found no evidence of original corner monument. Reestablished the corner mid-way and on-line between the section corners to the East and West. This position works well with the remains of an old hemlock stump, and the GLO distance to the stream to the West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D-9) 1/4 Corner Common to Sections 20 & 29, T. 46 N., R. 2 W.

Corner is a 3/4" re-bar with plastic Chippewa County Remonumentation Cap. The corner falls halfway down an embankment of the stream to the West.

Witnesses: 4" Maple N 50° E 1.31'
6" Spruce S 62° E 12.93'
12" Spruce S 09° E 7.97'
4" Maple N 77° W 12.10'
4" Maple N 21° W 8.80'

Bearings are compass bearings, corrected for declination, all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by William L. Karr

Date 12-30-96

Surveyor's Michigan License No. 27450

