MAR 27 1996

11.

CHIPPEWA COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	For corners in COMMISSION		Filing Requirement of Act 74, Mich. P.A. 1970	
	Chippewa			
	(County)	Located In:	Corner Code #	\$ 7.00 LAND CORNER
	1. Public Land Survey	T <u>46n</u> F T <u>45n</u> F T F	2W Dal Corner	\$ 2.00 MSSR 29 FEB 96 9:29 A.M. RECEIPT# 462 RFCFIUEN EDD DECOM
3	Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR		CHIFFENA LOUNTY - STATE OF NICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS
	4. Lot No Recor	ded Plat	L	Register of Deeds Stamp & File Number
	Larry R. Rogers			A B C D E F G H I J K L M
1	United States Department of the In hat the corner points mentioned in Board of Land Surveyors or by a ecovered, found as expressed belo	ules therefore as required terior, Bureau of Land Man Ilines 3, 4 and 5 above was Decree of a Court of the Co	October 2319 95 do hereby state that under provints mentioned in lines 1 and 2 above were in d in the current manual of survey instructions of the anagement or by a decree of a Court of Law and for vere in conformance with the rules of the Michigan Law; established, re-established, monumented, and range, may be recorded	4 7 8 9 10 11 12 6 18 17 16 15 14 13 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
Α	Description of original monu (D-13) South 1/4 1840: Austin Burt	ment and accessories Corner of Sect	s and/or subsequent restoration:	12 31 32 33 34 35 36
	1990: Gerald L. W	iggins, P.S. 2	3521. Corner recorded in Lib	19 links
	1990: Gerald L. Wiggins, P.S. 23521. Corner recorded in Liber 7, Page 244 of the Chippewa and Southwest corners of Section 32 with the following witnesses: 6" Balsam S58°E 21.3' Description of corner evidence found and/or method applied in restoring or reestablishing corner: Program. 19 links 19 links 10 Liber 7, Page 244 of the Chippewa and Southwest corners of Section 32 with the following witnesses: 4" Maple S72E 14.0' 6" Spruce N09°E 14.7' This corner is being perpetuated as part of the Chippewa County Remonumentation			
	TOURG BO estidone	-	ner position. Found "DNR Mon Accepted corner position as	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D-13) Corner is Michigan D.N.R. stamped aluminum Can on a a 3/4" iron pipe next to a wood RE OF MICHIG

Witnesses: 8" Spruce NO8°E 14.67' 6" Maple S75°E 8" Balsam 14.07' LARRY R. S61°E 21,24' 10" E1m ROGERS \$23°€ 10.481 Land Surveyor TO VIMENT NO. 29251 Signed by LAND AND TAKE TA Surveyor's Michigan License No. NOTE:

All bearings are compass bearings corrected for declination.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1975

REVISED MAY 14,1975

REVISED JAN., 1883

REVISED OCT., 1985 All bearings are compass bearings corrected for declination. All distances are to