CHIPPEWA COUNTY REMONUMENTATION CORNER

MAR 27 1996

LAND CORNER RECORDATION CERTIFICATE

| Filing Requirement of Act 74, Mich. P.A. | 1970 |
|--|--|
| | \$ 7.00 LAND CORNER \$ 2.00 MSSR |
| <u>Chippewa</u> Located In: Corner Code # | 29 FEB 96 9:32 A.M. RECEIPT# 462 |
| 1. Public Land Survey | RECEIVED FOR RECORD CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS |
| 2. Property Controlling S T R SIN Section S T SIN SECTION S SIN S SIN SECTION S SIN S SIN SECTION S SIN SECTION S SIN SECTION S SIN SECTION S SIN S SIN SECTION S SIN S SIN SECTION S SIN SECTION S SIN SECTION S SIN SECT | Register of Deeds Stamp & File Number |
| 4. Lot No, Recorded Plat | АВСОБЕБНІЈКЬ |
| 5. Private Claims | 1 |
| | 3 2 2 3 |
| I, Larry R. Rogers , in a field survey on Oct. 10, 19 95 do hereby state that und requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented recovered, found as expressed below: | in he 5 / 10 17 16 15 14 13 an |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. | 10 30 29 28 27 26 25 |
| | 11 |
| | 12 32 33 34 35 36 |
| (I-7) Southeast Corner of Section 15, T46N, R2W 1849: Harvey Mellen "set Tamarack post at Corner" with the following witnesses: 6" Tamarack S23E 23 links 8" Spruce N29W 40 links 1988: Neil E. Hill, P.S. 27447, found 1 3/4" diameter brass cap on rod, 1.7 feet below surface in monument box, 11.2 feet North of centerline of M-28 as referenced in 1941 Highway Plans (S-11-A-1) and recorded in Liber 7, Page 84 of the Chippewa County Corner Records with the following witnesses: P. Pole S40°E 78.41′ Guy Pole N40°E 80.10′ Chis. "X" SE Cor. Hdwl. W'ly end culvert S25°W 57.10′ Chis. "X" NE Cor. Hdwl. W'ly end culvert N12°W 61.06′ B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (I-7) This corner is being perpetuated as part of Chippewa County Remonumentation | |
| program. | |
| Found no evidence of original corner position. Found 1/2" iron in monument box (No brass cap) 11.2 feet North of the centerline of State Highway M-28. Recovered two witnesses from previous recording. Accepted corner position as found and established two new A CO witnesses. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (1-7) Corner is 1/2" iron pin in monument box 11.3 foot North of corners. | |
| C. Description of monument for corner and accessories established to perpetuate locating the $(1-7)$ Corner is $1/2$ " iron pin in monument box 11.2 feet Nor Highway M-28. | position of the corner: th of centerline of State |
| Witnesses: Guy Pole Top center of square Conc. R.O.W. Marker Utility Pole (DR4/111) "X" in West end of C.M.P. | N45°E 79.97′ N25°W 71.81′ S39°E 78.43′ S24°W 55.87′ |
| | S24°W 55.87' STATE OF MICHIGAN LARRY R. |
| Signed by Date 30 | DEC 1995 * ROGERS Land Surveyor |
| Surveyor's Michigan License No. 29251 | NO. 29251 |
| NOTE: Bearings are compass bearings corrected form APPROVEDBY MK for declination. Distances are to a nail in side of witness | The state of the s |

LIBER 9 PAGE 305