MOVENES

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Chippewa County Remonumentation Corner

For corners in

**Chippewa County** Located in: Corner Code # 1. Public Land Survey **T46N R7W** K-9 T R Ţ R T R 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S

BOOK 11 PAGE 116

\$7.00 LAND CURNER \$2.00 MSSR

23 FEB 2000 4:37:15 PM Receipt #21179 RECEIVED FOR RECORD

CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

G H ;

Register of Deeds Stamp & File Number

4. Lot No.

, Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on November 9, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

10 11

2 3 4

5

A. Description of original monument and accessories and/or subsequent restoration:

K-9 Corner Common to Sections 23, 24, 25, & 26, T46N, R7W

1850 - Original corner established by Wells Burt, a cedar post. Witnesses: Spruce 10, S22°E 22 links - Cedar 12, N53°W 22 links.

Found no evidence of subsequent restoration of this corner.

6 7 20 12

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Chippewa County Remonumentation Program. Found no evidence of the original corner. Reestablished corner by double proportionate measurement, using the section corner on the range line at M-9 to the east, the section corner at I-9 to the west, the section corner at K-11 to the south, and the south bank of the Tahquamenon River to the north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a ¾" x 24" rebar with a stamped aluminum Chippewa County Remonumentation cap at the corner location.

Nail and tag #33142 in 7" blazed Cedar, S33°W 51.70'

Nail and tag #33142 in 14" blazed Tamarack, N41°W 9.86' Nail and tag #33142 in 12" blazed Spruce, N38°E 18.97' Nail and tag #33142 in 11" blazed Cedar, S62°E 42.30'

MICHARA )بر MATERIA FROM SUBJECT Control of the contro SURVEYOR

Keith R. Wall

Date 12 - 29 - 99

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED JAN., 1983
REVISED OCT., 1995