

MAY 28 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner \$7.00 LAND CORNER

For corners in

| Chippewa County                    | Located in: | Corner Code # |
|------------------------------------|-------------|---------------|
| 1. Public Land Survey              | T46N R1E    | C-12          |
|                                    | T R         |               |
|                                    | T R         |               |
|                                    | T R         |               |
| 2. Property Controlling in Section | S T R       |               |
|                                    | S T R       |               |
| 3. Miscellaneous Property in Sec.  | S T R       |               |
|                                    | S T R       |               |
| 4. Lot No. , Recorded Plat         |             |               |
| 5. Private Claims                  |             |               |

\$2.00 MSSR  
 2/28/1997 3:12:41 PM Receipt #217  
 RECEIVED FOR RECORD  
 CHIPPEWA COUNTY - STATE OF MICHIGAN  
 SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 9 PAGE 375

Register of Deeds Stamp & File Number

| A  | B  | C  | D  | E  | F  | G  | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|
| 2  | 6  | 5  | 4  | 3  | 2  | 1  |   |   |   |   |   |   |
| 3  |    |    |    |    |    |    |   |   |   |   |   |   |
| 4  | 7  | 8  | 9  | 10 | 11 | 12 |   |   |   |   |   |   |
| 5  |    |    |    |    |    |    |   |   |   |   |   |   |
| 6  | 18 | 16 | 15 | 14 | 13 |    |   |   |   |   |   |   |
| 7  |    |    |    |    |    |    |   |   |   |   |   |   |
| 8  | 19 | 20 | 21 | 22 | 23 | 24 |   |   |   |   |   |   |
| 9  |    |    |    |    |    |    |   |   |   |   |   |   |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 |   |   |   |   |   |   |
| 11 |    |    |    |    |    |    |   |   |   |   |   |   |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 |   |   |   |   |   |   |
| 13 |    |    |    |    |    |    |   |   |   |   |   |   |

I, William L. Karr, in a field survey on October 15, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C-12) 1/4 Corner Common to Sections 31 & 32, T. 46 N., R. 1 E.

1845 J.H. Mullett in Original Survey, 10" Maple for 1/4 Section Post.

1898 F.H. Brown in records in County Surveyors Office show that no evidence of the Original Corner was found and the mile was divided up evenly, 1467.5 x 4.

1918 F.H. Brown in records in County Surveyors Office again show the mile evenly divided as in 1898.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-12) 1/4 Corner Common to Sections 31 & 32, T. 46 N., R. 1 E.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found 1/2" iron with cap set by R. Bischer, PS 22428, at the intersection of old and well established fence lines North, South and West, and an old fallen down fence to the East. Bischer's corner falls 1' North and 3' West of being on line and an even division of the mile.

Accepted Bischer's iron for the 1/4 corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C-12) 1/4 Corner Common to Sections 31 & 32, T. 46 N., R. 1 E.

Corner is a 1/2" iron with plastic cap no. 22428 set on the South side of a fence post at the intersection of fences North, South, East and West.

|            |                 |         |        |
|------------|-----------------|---------|--------|
| Witnesses: | 10" Aspen       | N 50° E | 45.40' |
|            | Fence Post      | S 84° E | 8.50'  |
|            | 8" Maple        | N 80° W | 56.45' |
|            | 15" White Birch | N 34° W | 37.46' |

Bearings are compass bearings, corrected for declination, all distances are to a nail with a Bischer Survey tag on the side of the witness objects.

Signed by William L. Karr

Date 12-30-96

Surveyor's Michigan License No. 27450

